
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: 4/21/2009
Test to be performed: Smoke Dyed Water X	Ground Condition: Dry ✓ Damp □ Wet □	Supervisor: <u>JAW</u>
Manhole_ID: S03K_013MH	Test ID: <u>D1032-002005</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S03K013MH
0			Water Level	
0			Dye Test Visible	5 GAL IN MANHOLE, sewer/MH connectio
4			Dye Test Visible	@ IR, 2 GPM
4	04		Infil Runner	@ jt
19.5			Dye Test Visible	@ IR, 1 GPM
19.5	04		Infil Runner	@ jt
21.70000076			Abandoned Survey	NO MORE DYE SEEN